

SGS ITALIA S.p.A.
ORGANISMO NOTIFICATO N. 1381

Industrial
 Via Caldera, 21
 20153 Milano
 Tel. (02) 7393.1 Fax: (02) 70125067
 Affiliate code 095103

Id. : CER.CPR. Strutture acciaio e Alluminio
 Rev. 1

Page 1 of 1

FILE N. 75.18.14772

Certificate of Conformity of the Factory Production Control

1381-CPR-515

Venice, 3rd April 2018

In compliance with Regulation 305/2011/EU of the European Parliament and of the Council of 9 March 2011 (the Construction Product Regulation or CPR), this certificate applies to the construction product

Structural Steel Components

Produced by

Manufacturer :	NS-TERMOMONTAŽA DOO
Legal Address:	Stevana Mokranjica br. 18 – 21000 – Novi Sad – Serbia
Production sites:	Rumenački put – 21000 – Novi Sad – Serbia

This certificate attests that all provisions concerning the assessment and verification of constancy of performance at system 2+ and the performances described in Annex ZA of the standards

UNI EN 1090-1:2012

***Production of structural steel components.
 To Execution class EXC2 according to EN 1090-2
 According to UNI EN ISO 3834-2
 Methods of Declaration: 3a***

are applied and that the product and the Factory Production Control fulfills all the prescribed requirements. This certificate has been issued on the **3rd April 2018** and will remain valid as long as the harmonized standard remains valid or the manufacturing conditions in the plant or the factory production control itself are not modified significantly.

This certificate is a translation of the original certificate nr. 1381-CPR-515 in Italian language and must not be used for any legal interpretation.

Date of last issue **3rd April 2018**

Position: RC CE

Name: Renato Donadel

The Authorized Representative

Signature.....



Member of **SGS** (Société Générale de Surveillance) Group



Any unauthorized alteration, forgery or falsification of the content or appearance of this document is unlawful and offenders may be prosecuted to the fullest extent of the law. The SGS stamp and signature merely represents receipt of the document and SGS makes no representations as to the accuracy, adequacy and/or completeness of third party test laboratory results, reports or certifications. Any holder of this document is advised that the information contained hereon is limited to visual examination of the safely and readily accessible portions of the consignment only. Solely for services related to witnessing/observing a third party's intervention(s) in accordance with Client's instructions, the Company's involvement has been limited to witnessing/observing a third party's intervention(s) at the third party's laboratory/test house or other facilities and installations used for the intervention(s). The Company's sole responsibility was to be present at the time of the third party's intervention(s) to forward the results, or confirm the occurrence, of the intervention(s). The Company is not responsible for the condition or calibration of apparatus, instruments and measuring devices used, the analysis methods applied the qualifications, actions or omissions of the third party's personnel or the analysis results.